


Vehicle	
Make	Buick
Model	Test
VIN	
Year	
Plate No.	1234

Client	
Name	VEC Development SRL
Address	Ion Neculce 47



Panel	Dents
Hood	D1: 0 D2: 10 D3: 0
Right Rear Door	D1: 0 D2: 15 D3: 0
Windshield Frame	D1: 20 D2: 0 D3: 0

PDR	USD	1.00
R-and-I	USD	0.00
Total	USD	1.00

Dents: 45

Panel status

- PDR
- R&R
- No Damage
- hOff
- Change
- TD Technical dents

Dent size

- Light dents
- Medium dents
- Strong dents

Total excl. VAT	USD	1.00
VAT (20%)	USD	0.20
Total incl. VAT	USD	1.20